




Mitnehmersteine

für Quernutfräserdorn



| Größe | b2 | k | h | a | Artikel-Nr. |
|-------|------|-----|----|------|-------------|
| 16 | 13,3 | 8 | 10 | 9,3 | MS16-Q |
| 16 | 13,3 | 7,9 | 8 | 9,3 | MS16-Q-1 |
| 16 | 16 | 8 | 8 | 10 | MS16-Q-2 |
| 22 | 17,6 | 10 | 12 | 10,6 | MS22-Q |
| 22 | 17,6 | 10 | 9 | 10,6 | MS22-Q-1 |
| 22 | 17,6 | 10 | 7 | 10,6 | MS22-Q-4 |
| 22 | 16 | 10 | 6 | 11 | MS22-Q-5 |
| 27 | 21,3 | 12 | 10 | 13,3 | MS27-Q |
| 32 | 22 | 14 | 14 | 13 | MS32-Q |
| 40 | 23 | 16 | 16 | 15 | MS40-Q |
| 50 | 24 | 18 | 20 | 16 | MS50-Q |

für Deckel



| b2 | k | h | Artikel-Nr. |
|----|------|---|-------------|
| 27 | 15,8 | 6 | MS15,8-6-27 |
| 27 | 15,8 | 8 | MS15,8-8-27 |